

**BULLETIN #:** 19M-01

**SUPERSEDES:** New  
**DATE:** Mar-11-2019  
**AUTHOR:** W. Hirsh



**SUBJECT: Obsolescence of 5F (New only) Compressor Models**

TECHNICAL

MARKETING


Page 1 of 1

Products Affected:  06D     06E     06CC     06M     06U     06V  
 5F     5H     05G     05K  
 06TA/TR     06TS-TT-TU-TV

**Description: Suspension of NEW 5F compressor production**

Production of all new 5F20, 5F30, 5F40, and 5F60 compressors is being suspended effective immediately due to supplier issues with some of the critical components. Carlyle® Customer Service will be in contact with any customers to help manage any current open orders for these compressors. Until further notice, Carlyle cannot accept any new orders for these compressors.

The figure below shows potential model conversion options to the existing 05K and 05G compressor platforms. Any belt driven applications should find a replacement model that has the same compressor displacement (i.e. capacity) as the legacy 5F model. However, this may be at a different compressor speed necessitating different pulley ratios on the drive system. Direct drive applications may require variable speed drives in order to compensate for these displacement differences.



This notice does not affect the remanufactured 5F compressor models. Carlyle will continue to accept and fulfil orders for these remanufactured 5F models, subject to the normal constraints associated with core availability.